



Dealer Advisory

Shipped Mower Key Location

| | |
|-----------------------|--|
| Advisory Type | Informational |
| Affected Units | All mowers equipped with key switch. |
| Situation | Dealers have reported keys being left on causing the hour meter to run up, batteries to drain, and/or lost keys. |
| Factory Action | Assembly and Shipping have been made aware of this issue and are instructed to make sure the key is attached to the deck lifting pedal with a breakaway zip-tie. |
| Dealer Action | Communicate this information to appropriate employees. |

